

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

### Sutter Maintenance Yard Maintenance Area 0016

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River	Right	4.06	04/04/2019 04/04/2019	Sterling York

LM Start		Rating **	A	Issue No.	3
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals				
DWR ID	DWR_MA0016_01_s _ 2013_3				
Comment Code					
Inspector Comment					
SBFCA has turned over levee to MA 16. The O&M manuals are located at the Sutter Maintenance Yard.					

No Photos

LM Start		Rating **	A	Issue No.	4
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training				
DWR ID	DWR_MA0016_01_s _ 2013_4				
Comment Code					
Inspector Comment					
Sutter maintenance yard employees attend the annual Flood Fight class put on by DWR.					

No Photos

LM Start		Rating **	A	Issue No.	5
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment				
DWR ID	DWR_MA0016_01_s _ 2013_5				
Comment Code					
Inspector Comment					
Emergency supplies and equipment are stored at the Sutter Maintenance Yard.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019**

**Sutter Maintenance Yard Maintenance Area 0016**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River	Right	4.06	04/04/2019 04/04/2019	Sterling York

LM Start	0.01	Rating **	A	Issue No.	7
LM End	4.06	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.255931 °	39.310941 °
				-121.636394 °	-121.637634 °
DWR ID	DWR_MA0016_01_s_2019_7				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
The annual vegetation is well maintained, Spring 2019.					

Photo 1 of 1 : SP\_2019\_MA0016\_302\_7\_20190409\_00011.jpg



View looking upstream landside at the well maintained vegetation, Spring 2019.

LM Start	0.01	Rating **	A	Issue No.	8
LM End	4.06	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.255931 °	39.310941 °
				-121.636394 °	-121.637634 °
DWR ID	DWR_MA0016_01_s_2019_8				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
The annual vegetation is well maintained, Spring 2019.					

Photo 1 of 1 : SP\_2019\_MA0016\_302\_8\_20190409\_00012.jpg



View looking upstream waterside at the well maintained vegetation, Spring 2019.

\* Location  
LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

### Sutter Maintenance Yard Maintenance Area 0016

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River	Right	4.06	04/04/2019 04/04/2019	Sterling York

LM Start	3.39	Rating **	M	Issue No.	15
LM End	3.39	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP LMA Responsibility		39.301218 °	39.301218 °	
			-121.638332 °	-121.638332 °	
DWR ID	17125				

**Comment Code**

**Inspector Comment**

FS\_ID:54027  
DS\_ID:17125  
EP\_NO: N/A  
Repair Type: Non-Urgent  
Crossing Status: Found  
UCIP Comments: 05/22/2019 (O. Magana - DWR UCIP)05/22/2017  
LS inlet buried. WS access being blocked off by over grown vegetation. Pipe has been selected for internal cleaning and inspection as part of the DMP project. (DWR Sutter Yard - AFreitag)12/01/2016  
LS inlet completely buried. (DWR Sutter Yard- AFreitag)05/26/2016  
LS inlet was completely buried.06/08/2015 Concrete headwall is still cracked and inlet is buried. It was said to be replaced with the SBFCA project but the project skipped over in this area.12/29/2014 Same as last inspection.05/19/2014 Same as last inspection.11/06/2013 Same as last inspection.05/14/2013 SBFCA project recommends replacing in accordance with title 23. Same as last inspection.12/11/2012 Concrete headwall on LS toe is cracked through middle and pipe is buried in soil. pipe appears corroded. (DWR UCIP - W. Wylie)  
FIELD\_STRUCT\_DESC: 1 of 2: 24-inch corrugated metal drainage pipe through the levee, 16.6 feet below the crown. Concrete headwalls on both the waterside (WS) and the landside (LS) ends. Flap gate on the WS end. [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 148, August 1955, (Station 646+96)].  
FS Date: 5/22/2019 3:47:39 PM

LM Start	3.39	Rating **	M	Issue No.	15 (cont)
LM End	3.39	Issue Type +	Ma	Location *	

Photo 1 of 2 : UCIP\_SP\_2019\_54027\_65782.jpg



Headwall at LS toe is cracked and the inlet is buried in soil.

Photo 2 of 2 : UCIP\_SP\_2019\_54027\_65781.jpg



Headwall on WS toe with flap gates.

* Location LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	---	--	---	--	--	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

### Sutter Maintenance Yard Maintenance Area 0016

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River	Right	4.06	04/04/2019 04/04/2019	Sterling York

LM Start	4.07	Rating **	A/W	Issue No.	17
LM End	4.07	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.311127°	39.311127°
				-121.637606°	-121.637606°
DWR ID	17123				

Comment Code
--------------

Inspector Comment
-------------------

FS\_ID:54030  
DS\_ID:17123  
EP\_NO: N/A  
Repair Type: No Action Needed  
Crossing Status: Found  
UCIP Comments: 05/22/2019 (O. Magana - DWR UCIP)05/22/2017 Crossing appears to be in good condition. (DWR Sutter Yard - AFreitag)12/01/2016 Crossing appears to be in good condition. (DWR Sutter Yard- AFreitag)05/26/2016 Crossing appears to be in good condition.06/08/2015 Pipe appears to be in good condition. No noticeable issues to report. Pipe was listed to be replaced with the SBFCA project but the project did not take place in this area.12/29/2014 Same as last inspection.05/19/2014 Same as last inspection.11/06/2013 Same as last inspection.05/14/2013 Slide gate opened allowing water to flow through, debris problem has been cleared and the gates seem to be functioning properly. SBFCA project recommends replacing in accordance with title 23.12/11/2012 Lock missing from concrete well access door-this should be resplaced. Some debris blocking preventing flapgate from completely closing. (DWR UCIP - W. Wylie)  
FIELD\_STRUCT\_DESC: 48-inch by 72-inch reinforced concrete drainage culvert through the levee, 20.5 feet below the crown. Slide gate in a concrete well on the waterside (WS) slope. Siphon breaker/air vent on the WS shoulder at the concrete well. [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 148, August 1955, (Station 683+25)].  
FS Date: 5/22/2019 3:50:14 PM

Photo 1 of 3 : UCIP\_SP\_2019\_54030\_65785.jpg



Slide gate, concrete well, siphon breaker/air vent and open channel on WS of levee.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

### Sutter Maintenance Yard Maintenance Area 0016

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River	Right	4.06	04/04/2019 04/04/2019	Sterling York

LM Start	4.07	Rating **	A/W	Issue No.	17 (cont)	
LM End	4.07	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.311127°	39.311127°	
				-121.637606°	-121.637606°	
DWR ID	17123					
Comment Code						
Inspector Comment						
FS_ID:54030 DS_ID:17123 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: 05/22/2019 (O. Magana - DWR UCIP)05/22/2017 Crossing appears to be in good condition. (DWR Sutter Yard - AFreitag)12/01/2016 Crossing appears to be in good condition. (DWR Sutter Yard- AFreitag)05/26/2016 Crossing appears to be in good condition.06/08/2015 Pipe appears to be in good condition. No noticeable issues to report. Pipe was listed to be replaced with the SBFCA project but the project did not take place in this area.12/29/2014 Same as last inspection.05/19/2014 Same as last inspection.11/06/2013 Same as last inspection.05/14/2013 Slide gate opened allowing water to flow through, debris problem has been cleared and the gates seem to be functioning properly. SBFCA project recommends replacing in accordance with title 23.12/11/2012 Lock missing from concrete well access door-this should be replaced. Some debris blocking preventing flapgate from completely closing. (DWR UCIP - W. Wylie) FIELD_STRUCT_DESC: 48-inch by 72-inch reinforced concrete drainage culvert through the levee, 20.5 feet below the crown. Slide gate in a concrete well on the waterside (WS) slope. Siphon breaker/air vent on the WS shoulder at the concrete well. [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 148, August 1955, (Station 683+25)]. FS Date: 5/22/2019 3:50:14 PM						

LM Start	<b>4.07</b>	Rating **	A/W	Issue No.	<b>17 (cont)</b>
LM End	<b>4.07</b>	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP\_SP\_2019\_54030\_65784.jpg



Pumping plant and slide gate on LS across canal. (no access from levee).

Photo 3 of 3 : UCIP\_SP\_2019\_54030\_65783.jpg



Concrete headwall and flap gate on WS toe.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

### Sutter Maintenance Yard Maintenance Area 0016

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River	Right	4.06	04/04/2019 04/04/2019	Sterling York

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---